

## STM32CubeProgrammer release v2.18.0

### Introduction

This release note is updated periodically to keep abreast of the STM32CubeProgrammer (STM32CubeProg) evolution, problems, and limitations. Check the STMicroelectronics website at [www.st.com/stm32softwaretools](http://www.st.com/stm32softwaretools) for the latest version. For the latest release summary, refer to [Table 1](#).

**Table 1. STM32CubeProgrammer v2.18.0 release summary**

Type	Summary
Major release	<ul style="list-style-type: none"> <li>Added the support for the <a href="#">STM32N6 series</a></li> <li>Added the support for the <a href="#">STM32U3 series</a></li> <li>Added the support for the <a href="#">STM32WL3x</a> product line</li> <li>Added the support for devices in the <a href="#">STM32C0 series</a> with 64 Kbytes and 256 Kbytes of flash memory</li> <li>Updated the support for the <a href="#">STM32H7R3/7S3</a> and <a href="#">STM32H7R7/7S7</a> microcontrollers</li> <li>Updated the support for the STM32MP13xx, STM32MP15xx, STM32MP23xx, and STM32MP25xx microprocessors</li> <li>Updated the support for the <a href="#">STM32U5 series</a></li> <li><a href="#">X-CUBE-RSSe</a> support</li> <li>Synthetic option byte view</li> <li>Project mode</li> <li>J-Link WB stack install</li> </ul>

### Customer support

For more information or help concerning STM32CubeProgrammer, contact the nearest STMicroelectronics sales office or use the ST community at [community.st.com](http://community.st.com). For a complete list of STMicroelectronics offices and distributors, refer to the [www.st.com](http://www.st.com) webpage.

### Software updates

Software updates and all the latest documentation can be downloaded from the STMicroelectronics support webpage at [www.st.com/stm32cubeprog](http://www.st.com/stm32cubeprog).

# 1 General information

## 1.1 Overview

STM32CubeProgrammer is a tool that allows STM32 device programming through debug interfaces (JTAG and SWD) and bootloader interfaces (UART, USB, I<sup>2</sup>C, SPI, and CAN). The range of supported bootloader interfaces depends on the microcontroller connected. Refer to the *STM32 microcontroller system memory boot mode* application note (AN2606) for details.

The tool offers a wide range of features to program STM32 internal memories (flash memory, RAM, OTP, and others) and external memories, verify the programming content (checksum, verify during and after programming, compare with file), and automate STM32 programming.

The STM32CubeProgrammer package also offers the optional installation of the STM32 Trusted Package Creator tool, which is used to create secure firmware files for secure firmware install and update. For more information, refer to the *STM32 Trusted Package Creator tool software description* user manual (UM2238).

STM32CubeProgrammer supports STM32 32-bit microcontrollers and microprocessors based on the Arm<sup>®</sup> Cortex<sup>®</sup> processor.

*Note:* Arm is a registered trademark of Arm Limited (or its subsidiaries) in the US and/or elsewhere.



## 1.2 Host PC system requirements

### Supported operating systems and architectures

- Windows<sup>®</sup> 10 32 bits (x86) or 64 bits (x64), and Windows<sup>®</sup> 11 64 bits (x64)
- Linux<sup>®</sup>: Ubuntu<sup>®</sup> LTS 22.04 and LTS 24.04, and Fedora<sup>®</sup> 40
- macOS<sup>®</sup> 14 (Sonoma), macOS<sup>®</sup> 15 (Sequoia)

*Note:* Windows is a trademark of the Microsoft group of companies.

Linux<sup>®</sup> is a registered trademark of Linus Torvalds.

Ubuntu<sup>®</sup> is a registered trademark of Canonical Ltd.

Fedora<sup>®</sup> is a trademark of Red Hat, Inc.

macOS<sup>®</sup> is a trademark of Apple Inc., registered in the U.S. and other countries and regions.

### Software requirements

For STM32CubeProgrammer versions earlier than v2.6.0, the Java<sup>®</sup> SE Runtime Environment 1.8 (version 1.8.0\_121 or newer) must be installed by Oracle<sup>®</sup> (only Java<sup>®</sup> 8 is supported).

Since STM32CubeProgrammer version v2.6.0, the tool can be installed without prerequisite JRE™ installation, because the STM32CubeProgrammer release package contains a JRE™ bundling.

*Note:* After the Oracle<sup>®</sup> announcement related to the “End of Public Updates for Oracle JDK 8”, access to OpenJDK is possible via [adoptopenjdk.net](https://adoptopenjdk.net).

*Note:* Oracle is a registered trademark of Oracle and/or its affiliates.  
All other trademarks are the property of their respective owners.

## 1.3 Setup procedure

Refer to the *STM32CubeProgrammer software description* user manual (UM2237) available at [www.st.com](http://www.st.com).

## 1.4 Licensing

STM32CubeProg is delivered under the SLA0048 software license agreement and its Additional License Terms.

## 2 STM32CubeProgrammer v2.18.0 release information

### 2.1 New features

- Added the support for the [STM32N6 series](#)
  - OTP programming
  - External memory programming
  - Serial boot via USB/UART
  - FSBL signature with `stm32header v2.3` through the signing tool
- Added the support for the [STM32U3 series](#)
  - Internal memory programming
  - Option byte/OTP programming
  - Core register programming
  - Regression with password (close/open)
  - SFI support
  - Key wrapping
  - Native services:
    - Key generation
    - Firmware encryption and signing
- Added the support for the [STM32WL3x](#) product line
  - Internal memory programming
  - Option byte/OTP programming
  - Firmware authentication
- Added the support for devices in the [STM32C0 series](#) with 64 Kbytes and 256 Kbytes of flash memory
  - Internal memory programming
  - Option byte/OTP programming
- Updated the support for the [STM32H7R3/7S3](#) and [STM32H7R7/7S7](#) microcontrollers
  - MCE encryption
- Updated the support for the STM32MP13xx, STM32MP15xx, STM32MP23xx, and STM32MP25xx microprocessors
  - PMIC NVM management
  - Support of STM32MPUSSP-UTIL
  - New *Secrets Gen* panel
- Updated the support for the [STM32U5 series](#)
  - Option byte recovery
- [X-CUBE-RSSe](#) support
- Synthetic option byte view
- Project mode: import/export settings
- J-Link WB stack install

Refer to the *STM32CubeProgrammer software description* user manual ([UM2237](#)) for details.

### 2.2 Fixed issues

**Table 2. Main issues fixed in STM32CubeProgrammer v2.18.0**

ID	Summary
106672	[STM32CubeProg] Install STM32CubeProgrammer in silent mode.
124828	[API][Qt] Request to update Qt® libraries for STM32CubeProgrammer API.
127932	[Automatic Mode] Save the configuration for automatic mode.

ID	Summary
140592	The start address of Flash-Bank2 is incorrect for the STM32U575VGT6 1-Mbyte flash memory.
148558	Recovery button for STM32U5 Cortex <sup>®</sup> -M33 MCUs.
156588	STM32U575xx 1-Mbyte part number programming does not work properly.
158636	[STM32H5] Unable to read/write/erase the external flash memory when TZEN is enabled.
159313	[Installer] Ability to install STM32CubeProgrammer via CLI.
160547	[ELF] Change file corrupted warning to be more specific.
162736	[STM32CubeProg][CLI]unable to modify the "unlock_2b" option byte value when programming option byte list (script).
165967	[GUI][Bootloader] Change "Error: RDP is set to level 1" to account for target under reset.
169161	[CLI][Write] STM32CubeProgrammer interprets an integer data as a hexadecimal number.
173328	[Documentation] Add more details about the number of bits on each write to the flash memory operation.
173662	[SPI][D450] Unable to program bank2 without skipping flash memory erase.
175637	[SDM][STM32H5][DA] Getting "PSA_LIFECYCLE_UNKNOWN" after running DA with nonsecure intrusive debug L3.
181058	[D466][Option bytes] Missing option bytes for 16-Kbyte part.
181262	[WB] DFUinterface issue with v2.16.
181382	[STM32H7] Wrong register bits description in STM32CubeProgrammer.
181704	[GUI/CLI] Erase sectors not working properly in STM32H503CB and STM32H503KB.
182020	[Database][D480] Wrong number/indexes of sectors for 1-Mbyte part.
182035	[GUI/CLI][STM32G4][J-Link] STM32CubeProgrammer fails to download via J-Link.
182053	[CLI][Linux] Text stays in bold after checking a version.
182758	[Flash loader][STM32L4] [FLASH][SWD] Sector erase failure for second memory bank.
184149	[DA][STM32H7Rx/7Sx] Wrong debug authentication chain.
185618	[DA] STM32CubeProgrammer dual NRST pulse issue in DISCOVERY mode.
186575	[CLI] STM32CubeProgrammer fails to erase EEPROM sector.
187833	[STM32H5 256 Kbytes] Issue with erasing sectors in Bank 2.
188096	[RDP] Unexpected error message is displayed when changing RDP level.
188098	[D451] Default flash memory size is displayed via bootloader interface.
188508	[D451] Wrong number of sectors for 1-Mbyte part in dual-bank via bootloader interface.
188642	[STM32H5][GUI] STM32CubeProgrammer halts and resumes MCU.
188714	[0x455][STM32U5 256 Kbytes] Missing configuration in database for device ID 0x455 with 256 Kbytes of flash memory.
188716	[Bootloader] STM32CubeProgrammer fails to erase sectors when SWAP_BANK=1.
188770	[CLI] Wrong message when using <code>-e1b1</code> option via USB.
188772	[Documentation][UM2237] Add a note to <code>-e1b1</code> description.
188857	[Bootloader][DBANK] STM32CubeProgrammer memory erasure issue via bootloader interface when DBANK=1.
189739	[Flash loader][STM32CubeIDE 1.16.0] Unable to debug with STM32L562-DK.
189999	[D479] Missing WRP option bytes on 256-Kbyte device.
190206	[GUI][J-Link] GUI crashes when trying to connect after closing STM32CubeProgrammer.
190543	[STM32CubeProg][STM32G474] Option byte write issue with J-Link.
191297	[Rev ID][STM32H56x] Revision ID does not appear.
191506	[Signing tool] Request to align key ID handling with the PKCS#11 standard.

ID	Summary
191898	OEM keys not present in the FastROM script.
193922	[STM32L4 256 Kbytes][0x435] Incorrect sector number and erasure issue in STM32CubeProgrammer.

## 2.3 Known problems and limitations

- Integrity check:
  - STM32H7 microcontrollers: support integrity check for SFI:
    - Only the devices with a bootloader version higher than 0x91 are supported.
    - STM32CubeProgrammer does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
  - STM32H73xxx microcontrollers: support integrity check for SFI/SFIx:
    - Only the devices with a bootloader version higher than 0x93 are supported.
    - STM32CubeProgrammer does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
  - STM32H7Bxxx microcontrollers: support integrity check for SFI/SFIx:
    - Only the devices with a bootloader version equal to or higher than 0x92 are supported.
    - STM32CubeProgrammer does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
- Auto mode (Linux® platform):
  - The SPI interface quits after starting without a connection.
- Debug authentication is not supported on Windows® 32 bits.
- SFIx fails for large flash memory content on Linux® via the UART interface.
- Unable to generate the CRC on an `.elf` file with relocated binary.
- USB interoperability issue on macOS® due to ST-LINK limitation.
- STM32G0 microcontrollers:
  - Option byte issue: impossible to decrease the RDP from the BB to AA state.
  - The `.hex` file does not modify the WRP and PCROP option bytes of bank 2 for the devices with 512 Kbytes of dual-bank flash memory.
- STM32H573xx microcontrollers:
  - Unable to read, write, or erase the external flash memory when TZEN is enabled
- STM32H7 microcontrollers:
  - STM32CubeProgrammer does not support SFI
- STM32H7Rx/7Sx microcontrollers:
  - Erasing the external flash memory is not supported using IWDG.
  - GUI: the external memory edition is not supported via USB and UART while connected to the OpenBootloader.
  - Option bytes are not supported via OpenBootloader interfaces.
- STM32L4R5xx microcontrollers:
  - Issues occur when erasing sectors in bank 2 memory with the UART interface
- STM32N6 microcontrollers:
  - Flash memory programming via the J-Link port is not supported
- STM32U3 microcontrollers:
  - Limited support via JTAG (functional only with mode = normal and reset = HWrst)

- STM32U5 microcontrollers:
  - STM32U535/545 microcontrollers: SFlx is not supported.
  - STM32U59xxx microcontrollers: SFlx only supports the area E installation with OTFDEC region 1 (region 0 on TPC).
  - STM32U59xxJ, STM32U5AxxJ, STM32U5Fxxx, and STM32U5Gxxx microcontrollers: wrong sector size when DBANK is equal to zero.
  - STM32U5Fxxx and STM32U5Gxxx microcontrollers: SFIA is not supported through SPI.
- STM32WBA microcontrollers:
  - OpenBootloader via SPI: cannot connect to STM32CubeProgrammer when the baud rate is below 3000 Bd.
  - “*Connect Under Reset*” is not working when called by STM32CubeIDE.

## 3 Previous release information

### 3.1 STM32CubeProgrammer v2.17.0 release information

#### 3.1.1 New features

- Added the support for the STM32MP25xx microprocessors in the [STM32MP2 series](#)
  - Flash memory and OTP programming, SSP support
- Added the support for devices in the [STM32WB0 series](#): STM32WB05 MCU, STM32WB05 coprocessor, STM32WB07 MCU, and STM32WB09 MCU product lines
  - Flash memory and OTP programming via debug and UART
  - Key generation, software signature, and OTP provisioning
- Added the support for new STM32C0xxxB microcontrollers in the [STM32C0 series](#) with 128 Kbytes of flash memory
  - Flash memory and OTP programming via debug and UART

Refer to the *STM32CubeProgrammer software description* user manual ([UM2237](#)) for details.

#### 3.1.2 Fixed issues

**Table 3. Main issues fixed in STM32CubeProgrammer v2.17.0**

ID	Summary
126305	[GUI][STM32U5] RDP regression with password level 2 not working on all operating systems.
129215	[STM32CubeProg] Add new features: save and load OB configurations.
136058	[STM32U575Z] STM32CubeProgrammer bug affecting flash memory programming when flash memory banks are swapped.
143616	[STM32CubeProg] Need to update the nswab_BANK description according to the new reference manual changes.
152836	[Flash loader][STM32CubeProg][STM32H5] When SWAP_BANK is enabled, bank 1 erasing is not functional.
168475	[STM32G4][GUI/CLI] Wrong description of BOOT_LOCK option byte.
171718	[STM32WL5x] An external flash loader generated with STM32CubeIDE does not work with STM32CubeProgrammer.
172137	Invalid .efl file if the path uses valid UTF-8.
172961	[DATABASE][D415] Programming failure via the bootloader interface in the second bank of a 1-Mbyte target.
175709	[UART] Sending an additional page to be erased.
175852	[Bootloader] Programming at the address 0x0Cxxxxxx via the bootloader interface.
175981	[DATABASE][D492] Wrong multiplier for SECW option bytes via the bootloader interface.
178135	STM32CubeProgrammer fails to program via the USB.
179072	[STM32C0][0x443] Missing configuration in database for device ID 0x443 with 16 Kbytes of flash memory.
179216	[API] Deallocate memory after read.
180037	Calling the obDisplay API crashes.

### 3.1.3 Known problems and limitations

- Integrity check:
  - STM32H7 microcontrollers: support integrity check for SFI/SMI:
    - Only the devices with a bootloader version higher than 0x91 are supported.
    - STM32CubeProgrammer does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
  - STM32H73xxx microcontrollers: support integrity check for SFI/SMI/SFIx:
    - Only the devices with a bootloader version higher than 0x93 are supported.
    - STM32CubeProgrammer does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
  - STM32H7Bxxx microcontrollers: support integrity check for SFI/SMI/SFIx:
    - Only the devices with a bootloader version equal to or higher than 0x92 are supported.
    - STM32CubeProgrammer does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
- Auto mode (Linux® platform):
  - The SPI interface quits after starting without a connection.
- Debug authentication is not supported on Windows® 32 bits.
- SFIx fails for large flash memory content on Linux® via the UART interface.
- Unable to generate the CRC on an `.elf` file with relocated binary.
- USB interoperability issue on macOS® due to ST-LINK limitation.
- STM32G0 microcontrollers:
  - Option byte issue: impossible to decrease the RDP from the BB to AA state.
  - The `.hex` file does not modify the WRP and PCROP option bytes of bank 2 for the devices with 512 Kbytes of dual-bank flash memory.
  - Unable to change the option bytes when WWDG\_SW and IWDG\_SW are unchecked.
- STM32G4 microcontrollers:
  - STM32CubeProgrammer fails to download via J-Link
  - STM32G491xx microcontrollers: Issues occur when erasing sectors in bank 2 memory
- STM32H573xx microcontrollers:
  - Unable to read, write, or erase the external flash memory when TZEN is enabled
- STM32H7 microcontrollers:
  - STM32CubeProgrammer does not support combined SFI and SMI.
  - SMI programming fails.
- STM32H7Rx/7Sx microcontrollers:
  - SFI is not supported.
  - Erasing the external flash memory is not supported using IWDG.
  - GUI: the external memory edition is not supported via USB and UART while connected to the OpenBootloader.
  - Option bytes are not supported via OpenBootloader interfaces.
- STM32MP25xx microprocessors:
  - SSP secret generation is not supported
- STM32U5 microcontrollers:
  - Impossible to modify the `unlock_2b` option byte value when programming the OB list.
  - STM32U535/545 microcontrollers: SFIx is not supported.
  - STM32U575VGT6: the start address of Flash-Bank2 is incorrect.
  - STM32U59xxx microcontrollers: SFIx only supports the area E installation with OTFDEC region 1 (region 0 on TPC).
  - STM32U59xxJ, STM32U5AxxJ, STM32U5Fxxx, and STM32U5Gxxx microcontrollers: wrong sector size when DBANK is equal to zero
  - STM32U5Fxxx and STM32U5Gxxx microcontrollers: SFIA not supported via SPI.



- STM32WBA microcontrollers:
  - OpenBootloader via SPI: cannot connect to STM32CubeProgrammer when the baud rate is below 3000 Bd.
  - “Connect Under Reset” is not working when called by STM32CubeIDE.

## 3.2 STM32CubeProgrammer v2.16.0 release information

### 3.2.1 New features

- Added the support for the [STM32U0 series](#)
    - Flash memory/option byte/OTP programming via the debug and bootloader interfaces
    - RDP regression with password
  - Added the support for the STM32H7Rx/7Sx microcontrollers in the [STM32H7 series](#)
    - Flash memory/option byte/OTP programming via the debug and bootloader interfaces
    - Debug authentication with a password or certificate
    - SFI support
  - Added the support for the STM32H523/533 microcontrollers in the [STM32H5 series](#)
    - Flash memory/option byte/OTP programming via the debug and bootloader interfaces
    - Debug authentication with a password or certificate
    - Authentication key provisioning
    - Key generation
    - Firmware encryption and signing
    - Certificate generation
    - SFI/SFIx support
  - Added the SFI support for the STM32WBA5xxx microcontrollers
  - Upgraded STM32CubeProgrammer to Qt 6
  - Added the support for the J-Link probe (SEGGER) without security features
  - Enhanced the security for the STM32H562 and STM32H563/H573 microcontrollers: new RSSe integrated
- Refer to the *STM32CubeProgrammer software description* user manual ([UM2237](#)) for details.

### 3.2.2 Fixed issues

**Table 4. Main issues fixed in STM32CubeProgrammer v2.16.0**

ID	Summary
120183	[GitHub] Issue with DFU programming on STM32F767xx MCUs.
147113	[STM32H5] Generation of <code>DA_Config.obk</code> , with only a public key as input, for the purpose of generating a file.
151099	[STM32F0][WRP] Wrong naming of WRP; STM32CubeProgrammer writes values to unused nWRP <sub>x</sub> /WRP <sub>x</sub> (x=1,2,3).
151146	[SWD][STLINK-V3] Wrong frequency displayed in CLI.
157815	[Device_ID=0x415][GUI] Mass erase and sector erase are not working properly via the ST-LINK interface.
159985	Issue in comparing noncontiguous files.
161502	[STM32CubeProg][D461 512K][STM32L496RET6] Issue to program a binary: erase a sector is not possible.
162313	[STM32G031GU6] Wrong flash memory size of 63 Kbytes instead of 16 Kbytes.
162318	[DATABASE][SWD] Wrong flash memory size for 512-Kbyte parts (Device_ID=0x413).
162579	[automode][OB] Extend CLI check on invalid values to auto mode.
163127	[OB][VERIFY] Wrong value read for HDP2EN in 32-bit operating system.
163297	[OB][STM32G4] Issue when displaying option bytes in CLI via UART bootloader.

ID	Summary
163444	[API] Compilation error occurs when <code>getStorageStructure()</code> is called.
163911	[API] The <code>editSector()</code> function is not working properly.
165977	[GUI][UART][DTR/RTS] Support controlling boot configuration via DTR/RTS in GUI.
166376	[BOR][DATABASE] Wrong description for BOR_LEV option byte.
166453	[GUI][CAN bootloader] Baud rate dropout menu missing the 1-Mbit/s speed.
168475	[STM32G4][GUI/CLI] Wrong description of the BOOT_LOCK option byte.
169892	[STM32H5][SWD] The flash memory is read as 0x00 when the boot is done from the system memory.
171611	[STM32U5][SWD] Unable to program internal memory in a specific OB config for 2-Mbyte parts.
171746	The SFI option bytes are not aligned with the reference manual.
172980	[STM32U5][TPC] Typo in SFI OB <code>.csv</code> files for STM32U5.

### 3.2.3 Known problems and limitations

- Integrity check:
  - STM32H7 microcontrollers: support integrity check for SFI/SMI:
    - Only the devices with a bootloader version higher than 0x91 are supported.
    - STM32CubeProgrammer v2.16.0 does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
  - STM32H73xxx microcontrollers: support integrity check for SFI/SMI/SFIx:
    - Only the devices with a bootloader version higher than 0x93 are supported.
    - STM32CubeProgrammer v2.16.0 does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
  - STM32H7Bxxx microcontrollers: support integrity check for SFI/SMI/SFIx:
    - Only the devices with a bootloader version higher than 0x92 are supported.
    - STM32CubeProgrammer v2.16.0 does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
- Auto mode (Linux® platform):
  - The SPI interface quits after starting without a connection.
- STM32G0 microcontrollers:
  - Option byte issue: impossible to decrease the RDP from the BB to AA state.
  - The `.hex` file does not modify the WRP and PCROP option bytes of bank 2 for the devices with 512 Kbytes of dual-bank flash memory.
  - Unable to change the option bytes when WWDG\_SW and IWDG\_SW are unchecked.
- STM32H523/533 microcontrollers:
  - Software reset is not performed after setting `product_State` to 0x2E via USB.
- STM32H523/533, STM32H562, and STM32H563/573 microcontrollers:
  - Wrong RSSe default filename in the SFI/SFIx panel.
- STM32H573xx microcontrollers:
  - Unable to read, write, or erase the external flash memory when TZEN is enabled
- STM32H7 microcontrollers:
  - STM32CubeProgrammer does not support combined SFI and SMI.
  - SMI programming fails.
- STM32H7Rx/7Sx microcontrollers:
  - Impossible to program the full extent of the external memory in one single shot with the OpenBootloader via USB. A workaround is to program in several runs of 64 Mbytes maximum.
  - GUI: the external memory edition is not supported via USB and UART while connected to the OpenBootloader.

- STM32U5 microcontrollers:
  - STM32U535/545 microcontrollers: SFlx is not supported.
  - STM32U575VGT6: the start address of Flash-Bank2 is incorrect.
  - STM32U59xxx microcontrollers: SFlx only supports the area E installation with OTFDEC region 1 (region 0 on TPC).
  - STM32U59xxx and STM32U5Axxx microcontrollers: wrong sector size when DBANK = 0 (16 Kbits instead of 8 Kbits).
  - RDP regression with password [level 2] is not supported on all platforms.
- STM32WBA microcontrollers:
  - OpenBootloader via SPI: cannot connect to STM32CubeProgrammer when the baud rate is below 3000 Bd.
- Debug authentication is not supported on Windows® 32 bits.
- SFlx fails for large flash memory content on Linux® via the UART interface.

### 3.3 STM32CubeProgrammer v2.15.0 release information

#### 3.3.1 New features

- Added the NOR flash memory and OTP fuse programming via USB and UART using OpenBootloader for the STM32MP13xx microprocessors
  - Added the support for the PMIC programming via UART for the STM32MP15xx microprocessors
  - Added limited FASTROM support
  - Added the automatic determination of the stack install address for the [STM32WB series](#) and [STM32WB0 series](#)
  - Enhanced security: the link to [sw-center.st.com](http://sw-center.st.com) is updated from STM32CubeProgrammer v2.15.0
- Refer to the *STM32CubeProgrammer software description* user manual ([UM2237](#)) for details.

#### 3.3.2 Fixed issues

**Table 5. Main issues fixed in STM32CubeProgrammer v2.15.0**

ID	Summary
110598	[STM32CubeProg][STM32WB] Incorrect installation address when the RF stack is already in place.
124075	[GUI][Device memory] Request to remove the <i>partitions</i> view from <i>Device memory</i> .
140915	[STM32L0][EEPROM] Error message when erasing the EEPROM via the ST-LINK interface.
145199	[STM32CubeProg-FUS] [STM32WB15xx] Missing the wireless stack version.
150022	[STM32F0][STM32CubeProg] Confusing naming and use of nWRP.
150428	[STM32WB][DFU] The <b>[Start Wireless Stack]</b> button is grayed in DFU mode.
153021	The STM32WB firmware upgrade of a large stack shows an error while it is passed.
153419	[Option bytes][Device_ID = 0x480] FLASH_OTPBL_PRG is missing from the OB list.
155082	Wrong RSS version displayed on STM32CubeProgrammer/CLI.
155918	[STM32CubeProg] The connection error popup cannot be closed using the <b>[X]</b> close button.
158082	[STM32L4][DBANK] Wrong sector size when DBANK is disabled.
158507	[DATABASE][OB] Missing nDBOOT OB for 1-Mbit targets.
159061	[Device_ID = 0x467][DATABASE] Remove testing on dual bank for the 128-Kbit flash memory size.
159172	[STM32CubeProg][API] Bank number is always zero due to a wrong name size in the <code>DeviceDataStructure.h</code> file: 32 instead of 64.
159589	Error returned by TPC when used embedded in STM32CubeMX.
160062	[DATABASE][OB] Write protection option bytes are not shown via the bootloader interface.

ID	Summary
161652	[SFI] Instability on STM32U5 microcontrollers with official release 2.14.0.

### 3.3.3 Known problems and limitations

- Integrity check:
  - STM32H7 microcontrollers: support integrity check for SFI/SMI:
    - Only the devices with a bootloader version higher than 0x91 are supported.
    - STM32CubeProgrammer v2.15.0 does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
  - STM32H73xxx microcontrollers: support integrity check for SFI/SMI/SFIx:
    - Only the devices with a bootloader version higher than 0x93 are supported.
    - STM32CubeProgrammer v2.15.0 does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
  - STM32H7Bxxx microcontrollers: support integrity check for SFI/SMI/SFIx:
    - Only the devices with a bootloader version higher than 0x92 are supported.
    - STM32CubeProgrammer v2.15.0 does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
- Auto mode (Linux® platform):
  - The SPI interface quits after starting without a connection.
- STM32G0 microcontrollers:
  - Option byte issue: impossible to decrease the RDP from the BB to AA state.
  - The `.hex` file does not modify the WRP and PCROP option bytes of bank 2 for the devices with 512 Kbytes of dual-bank flash memory.
- STM32H573xx microcontrollers:
  - Unable to read, write, or erase the external flash memory when TZEN is enabled
- STM32H7 microcontrollers:
  - STM32CubeProgrammer does not support combined SFI and SMI.
  - SMI programming fails.
- STM32U5 microcontrollers:
  - STM32U535xx and STM32U545xx microcontrollers: SFIx is not supported because of a limitation with RSSe.
  - STM32U575VGT6: the start address of Flash-Bank2 is incorrect.
  - STM32U58xxx and STM32U59xxx microcontrollers: for the SFIx area K, the size value must be 32-bit aligned inside the `.kcsv` file.
  - STM32U59xxx microcontrollers: SFIx only supports the area E installation with OTFDEC region 1 (region 0 on TPC).
  - STM32U59xxx and STM32U5Axxx microcontrollers: wrong sector size when DBANK = 0 (16 Kbits instead of 8 Kbits).
  - RDP regression with password [level 2] is not supported on all platforms.
- STM32WBA microcontrollers:
  - SFI is not supported.
  - OpenBootloader via SPI: cannot connect to STM32CubeProgrammer when the baud rate is below 3000 Bd.
- Debug authentication is not supported on Windows® 32 bits.
- SFIx fails for large flash memory content on Linux® via the UART interface.

## 3.4 STM32CubeProgrammer v2.14.0 release information

### 3.4.1 New features

- Updated the support for the entire [STM32H5 series](#):
  - Debug authentication with password or certificate
  - Authentication key provisioning
  - Key generation
  - Firmware encryption and signing
  - Certificate generation
  - SFI support, secure manager install, and module install/update
- Added support for microcontrollers in the [STM32L5 series](#) and [STM32WL series](#):
  - SFI integrity check
- Updated support for the [STM32U5 series](#):
  - SFI support for the [STM32U535/545](#), [STM32U575/585](#), [STM32U595/5A5](#), and [STM32U599/5A9](#) product lines
- Added support for the STM32U5Fxxx and STM32U5Gxxx microcontrollers:
  - SFI support: user interface and command-line interface
  - SFlx support:
    - Via debug: user interface and command-line interface
    - Via bootloader: command-line interface only

Refer to the *STM32CubeProgrammer software description* user manual ([UM2237](#)) for details.

### 3.4.2 Fixed issues

**Table 6. Main issues fixed in STM32CubeProgrammer v2.14.0**

ID	Summary
129635	[STM32MP15x] 128-Gbyte SD™ card programming error.
133771	[STM32U5] Unable to set the OEM1 and OEM2 keys through DFU.
136574	[STM32 MPU][GUI] Unable to program a .tsv file when some partitions are not selected.
143511	[STM32CubeProg][macOS][Ventura][USB][ST-LINK] STM32CubeProgrammer hangs during connect.
144488	[GUI] Offset on more than 32 bits is not handled properly.
145562	Periodic reading of bootloader version via ST-LINK.
145606	[Live Update] Disable checkbox on connect.
145769	[STM32CubeProg] Quiet mode is disabled when <code>-xdu</code> is used.
146512	[STM32CubeProg][STM32U5][OpenBootloader] Failing to run OpenBootloader correctly.
146515	[STM32CubeProg][CLI] SWV is working only on port 0.
148404	[SVD][STM32C0] Integrate STM32C0 SVD files.
149042	[Database] Unable to program target via bootloader interfaces (Device_ID = 0x467).
149212	[GUI] Deselect all buttons not working properly in external loaders tab.
149330	[STM32CubeProg][STM32G0B1CBTxD467] Wrong flash memory size for STM32G0B1 with 128 Kbits.
149467	[Database] Unable to program target via ST-LINK interfaces (Device_ID = 0x470)
150019	[STM32CubeProg][EL] Wrong display of custom EL sectors.

### 3.4.3 Known problems and limitations

- Integrity check:
  - STM32H7 microcontrollers: support integrity check for SFI/SMI:
    - Only the devices with a bootloader version higher than 0x91 are supported.
    - STM32CubeProgrammer v2.14.0 does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
  - STM32H73xxx microcontrollers: support integrity check for SFI/SMI/SFIx:
    - Only the devices with a bootloader version higher than 0x93 are supported.
    - STM32CubeProgrammer v2.14.0 does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
  - STM32H7Bxxx microcontrollers: support integrity check for SFI/SMI/SFIx:
    - Only the devices with a bootloader version higher than 0x92 are supported.
    - STM32CubeProgrammer v2.14.0 does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
- Auto mode (Linux® platform):
  - The SPI interface quits after starting without a connection.
- STM32G0 microcontrollers:
  - The `.hex` file does not modify the WRP and PCROP option bytes of bank 2 for the devices with 512 Kbytes of dual-bank flash memory.
  - The SWD `RegDump` command-line instruction does not work on STM32G081xx devices.
- STM32H503 microcontrollers:
  - A total of 64 bytes are programmed to the OTP area with STM32CubeProgrammer after password provisioning.
- STM32H7 microcontrollers:
  - STM32CubeProgrammer does not support combined SFI and SMI.
  - SMI programming fails.
- STM32MP15x microprocessors:
  - An error occurs when saving the OTP partition in a macOS® platform.
- STM32U5 microcontrollers:
  - STM32U535xx and STM32U545xx microcontrollers: SFIx is not supported because of a limitation with RSSe.
  - STM32U58xxx and STM32U59xxx microcontrollers: for the SFIx area K, the size value must be 32-bit aligned inside the `.kcsv` file.
  - STM32U59xxx microcontrollers: SFIx only supports the area E installation with OTFDEC region 1 (region 0 on TPC).
  - STM32U5F9xx and STM32U5G9xx microcontrollers: DK2 is not supported because there is no OTFDEC on HSP11.
  - RDP regression with password [level 2] is not supported on all platforms.
- STM32WBA microcontrollers:
  - SFI is not supported.
  - OpenBootloader via SPI: cannot connect to STM32CubeProgrammer when the baud rate is below 3000 Bd.
- Azure® RTOS USBX:
  - For STM32U575/585 microcontrollers, erasing sectors from "C" to "F" fails.
  - For STM32U575/585 microcontrollers, some extra data is added at memory programming.
- Debug authentication is not supported on Windows® 32 bits.
- SFIx fails for small flash memory content on supported bootloader interfaces with all platforms.

## 3.5 STM32CubeProgrammer v2.13.1 release information

### 3.5.1 New features

- No new feature in STM32CubeProgrammer v2.13.1.  
Refer to the sections [Fixed issues](#) and [Known problems and limitations](#) for details.

### 3.5.2 Fixed issues

Enhancements with macOS®.

### 3.5.3 Known problems and limitations

- Integrity check:
  - STM32H7 microcontrollers: support integrity check for SFI/SMI:
    - Only the devices with a bootloader version higher than 0x91 are supported.
    - STM32CubeProgrammer v2.13.0 does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
  - STM32H73xxx microcontrollers: support integrity check for SFI/SMI/SFIx:
    - Only the devices with a bootloader version higher than 0x93 are supported.
    - STM32CubeProgrammer v2.13.0 does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
  - STM32H7Bxxx microcontrollers: support integrity check for SFI/SMI/SFIx:
    - Only the devices with a bootloader version higher than 0x92 are supported.
    - STM32CubeProgrammer v2.13.0 does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
- Auto mode (Linux® platform):
  - The SPI interface quits after starting without a connection.
- STM32G0 microcontrollers:
  - The `.hex` file does not modify the WRP and PCROP option bytes of bank 2 for the devices with 512 Kbytes of dual-bank flash memory.
  - The SWD `RegDump` command-line instruction does not work on STM32G081xx devices.
- STM32H5 microcontrollers:
  - SFI and SSFI (secure manager) are not supported.
- STM32H503 microcontrollers:
  - A total of 64 bytes are programmed to the OTP area with STM32CubeProgrammer after password provisioning.
- STM32H563/573 microcontrollers:
  - The high-cycle data programming of flash memory is not supported.
- STM32H7 microcontrollers:
  - STM32CubeProgrammer does not support combined SFI and SMI.
  - SMI programming fails.
- STM32MP15x microprocessors:
  - It is not possible to program a `.tsv` file when some partitions are not selected.
  - An error occurs when saving the OTP partition in a macOS® platform.
- STM32U5 microcontrollers:
  - RDP regression with password is not working on macOS®.
  - It is impossible to set OEM keys through DFU.
  - STM32U59xxx microcontrollers: SFIx only supports the area E installation with OTFDEC region 1 (region 0 on TPC).
  - STM32U58xxx and STM32U59xxx microcontrollers: for the SFIx area K, the size value must be 32-bit aligned inside the `.kcsv` file.

- STM32WBA microcontrollers:
  - SFI is not supported.
  - OpenBootloader via SPI: cannot connect to STM32CubeProgrammer when the baud rate is below 3000 Bd.
- Azure<sup>®</sup> RTOS USBX:
  - For STM32U575/585 microcontrollers, erasing sectors from "C" to "F" fails.
  - For STM32U575/585 microcontrollers, some extra data is added at memory programming.
- Debug authentication is not supported on macOS<sup>®</sup> and Windows<sup>®</sup> 32 bits operating systems.
- The input of checksum files other than .bin files is not supported in the GUI.
- The maximum firmware size for SFx generation with STM32U599xx/595xx/5A5xx microcontrollers is limited to 3 Mbytes.

## 3.6 STM32CubeProgrammer v2.13.0 release information

### 3.6.1 New features

- Added support for the [STM32H5 series](#):
  - [STM32H563/573](#)
    - Debug authentication with password or certificate
    - Authentication key provisioning
    - Key generation
    - Firmware encryption and signing
    - Certificate generation
  - [STM32H503](#)
    - Debug authentication with password or certificate
    - Firmware encryption and signing
- Added support for the [STM32WBA series](#):
  - Flash memory and OTP programming, and option bytes
- Updated support for the [STM32U5 series](#):
  - [STM32U535/545](#):
    - SFI support (user interface and command-line interface)  
Flash memory, option bytes, RDP regression with password, and OTP programming.
  - [STM32U595/5A5](#):
    - SFI update (user interface and command-line interface)
    - SFIx update
      - Via debug: user interface and command-line interface
      - Via bootloader: command-line interface only
- Added support for the [STLINK-V3PWR](#):
  - Debug
  - Bridge to bootloader interfaces (SPI, I<sup>2</sup>C, and CAN)
- Added new calculator features:
  - Number converter
  - File and flash memory checksum

### 3.6.2 Fixed issues

**Table 7. Main issues fixed in STM32CubeProgrammer v2.13.0**

ID	Summary
65657	Add the checksum display as done for the ST-LINK utility.



ID	Summary
115829	[TrustedPackageCreator] Register naming mismatch between reference manual and .csv file.
116552	Possible attack on OEM1KEY and OEM2KEY.
129709	External flash memory programming issues in auto mode.
132975	[STM32G0] <i>Erase selected sectors</i> does not work properly on 256-Kbyte devices.
135017	[STM32CubeProg-GUI] Message must be updated while disabling RDP regression with password value.
135436	[API] Unhandled exception in <code>writeMemory()</code> .
136195	[STM32CubeProg][STM32C0] STM32C031C4T6: wrong flash memory size.
136233	[CLI] ST-LINK serial number is ignored in shared mode.
137687	[CLI] Missing data from hex file when using <code>safelib</code> .
138051	[STM32CubeProg] STM32L5 CLI displaying protected flash memory content.
140627	[STM32CubeProg][STM32G4 256 Kbytes][0x495] <i>Erase selected sectors</i> does not work properly on 256-Kbyte devices with dual-bank mode (reopen).
140973	[STM32CubeProg-Connection] Connection issues for STM32G031J4M6.
141725	[STM32CubeProg][STM32G0 0x466] User configuration option bytes programming failed.
142009	[[STM32CubeProg-Register_Viewer] NVIC_ISEr[1-4] addresses are incorrect in the register viewer.
142286	[STM32H5][STM32CubeProg] Cannot erase the flash memory when TZEN=0.

### 3.6.3 Known problems and limitations

- Integrity check:
  - STM32H7 microcontrollers: support integrity check for SFI/SMI:
    - Only the devices with a bootloader version higher than 0x91 are supported.
    - STM32CubeProgrammer v2.13.0 does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
  - STM32H73xxx microcontrollers: support integrity check for SFI/SMI/SFIx:
    - Only the devices with a bootloader version higher than 0x93 are supported.
    - STM32CubeProgrammer v2.13.0 does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
  - STM32H7Bxxx microcontrollers: support integrity check for SFI/SMI/SFIx:
    - Only the devices with a bootloader version higher than 0x92 are supported.
    - STM32CubeProgrammer v2.13.0 does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
- Auto mode (Linux® platform):
  - The SPI interface quits after starting without a connection.
- STM32G0 microcontrollers:
  - The .hex file does not modify the WRP and PCROP option bytes of bank 2 for the devices with 512 Kbytes of dual-bank flash memory.
  - The SWD `RegDump` command-line instruction does not work on STM32G081xx devices.
- STM32H5 microcontrollers:
  - SFI and SSFI (secure manager) are not supported.
- STM32H503 microcontrollers:
  - A total of 64 bytes are programmed to the OTP area with STM32CubeProgrammer after password provisioning.
- STM32H7 microcontrollers:
  - STM32CubeProgrammer does not support combined SFI and SMI.
  - SMI programming fails.

- STM32MP15x microprocessors:
  - It is not possible to program a `.tsv` file when some partitions are not selected.
  - An error occurs when saving the OTP partition in a macOS® platform.
- STM32U5 microcontrollers:
  - RDP regression with password is not working on macOS®.
  - It is impossible to set OEM keys through DFU.
  - STM32U59xxx microcontrollers: SFlx only supports the area E installation with OTFDEC region 1 (region 0 on TPC).
  - STM32U58xxx and STM32U59xxx microcontrollers: for the SFlx area K, the size value must be 32-bit aligned inside the `.kcsv` file.
- STM32WBA microcontrollers:
  - SFI is not supported.
  - OpenBootloader via SPI: cannot connect to STM32CubeProgrammer when the baud rate is below 3000 Bd.
- Azure® RTOS USBX:
  - For STM32U575/585 microcontrollers, erasing sectors from "C" to "F" fails.
  - For STM32U575/585 microcontrollers, some extra data is added at memory programming.
- Debug authentication is not supported on macOS® and Windows® 32 bits operating systems.
- The input of checksum files other than `.bin` files is not supported in the GUI.
- The maximum firmware size for SFlx generation with STM32U599xx/595xx/5A5xx microcontrollers is limited to 3 Mbytes.

## 3.7 STM32CubeProgrammer v2.12.0 release information

### 3.7.1 New features

- STM32 Trusted Package Creator: enhanced SFI UI
- [STM32MP1 series](#): added SSP GUI
- [STM32WB series](#): upgraded the wireless stack and enhanced the UI
- [STM32WL series](#): added module support
- Script manager: added loops and conditional statements
- External flash memory programmer: added [B-U585I-IOT02A](#) for SFlx
- [32F746GDISCOVERY](#) and [STM32F7508-DK](#): new external flash loaders

### 3.7.2 Fixed issues

**Table 8. Main issues fixed in STM32CubeProgrammer v2.12.0**

ID	Summary
116538	[STM32CubeProg] Address is always equal to 0x0 when saving <code>.bin</code> as <code>.hex</code> file.
117842	[STM32CubeProg - STM32L0] EEPROM banks are erased for one EEPROM bank selected.
119632	[STM32L5][TZEN - Regression] Error occurred when TZEN regression field is checked.
122194	[API][ST-LINK] No error message displayed when the MCU is not powered.
122254	[STM32CubeProg - Documentation] Confusing behavior when running <code>-log</code> option without file specification.
123745	[STM32CubeProg][STM32MP1] Even if SWD is not supported for STM32MP1, STM32CubeProgrammer should not crash when trying to connect via SWD/JTAG.
123960	[GUI] Switching from one section to another in the OB panel does not keep the OB box modified status.
126294	[STM32CubeProg] Device connection issue after increasing the RDP level.
127191	[STM32MP157] Unselecting TSV partitions times out while programming.
127922	[CLI] CMD failure ( <code>Error cmd</code> ) should interrupt the execution of the script.

ID	Summary
128988	[STM32CubeProg-GUI] STM32G0B0xx device missing from device list with ID 0x467.
130116	[STM32CubeProg] Error while programming a .bin file with more than 128 Kbyte flash memory size into an STM32L081xZ device.
130186	[STM32CubeProg] “start address” in download page is grayed while filename extension .BIN is uppercase.
130479	[GUI] “Select MCU” & “Program HSM” buttons must be grayed for a programmed HSM.
131027	[STM32CubeProg - Signing tool] Issue with SC-HSM / PKCS#11.
131245	[Documentation][UM2237][SWV][CLI] Add explanation for <code>-startswv</code> .
131307	[SFI on STM32H735xx] SFI window hanging.
131765	[STM32CubeProg][Flash loader] STM32CubeProgrammer does not accept external loader file name containing more than one dot.
131834	[STM32WB][Stack update] Request to change the error message when trying to update stack with anti-rollback activated without previous stack load.
131987	[CLI][Error level] Program returned 0 error code when error occurred.
132049	[DDR][CLI] Error occurs when loading DDR tool via the USB.
132213	[STM32CubeProg - GUI] Mismatch between STM32WB35xx reference manual and STM32CubeProgrammer database.
132528	[STM32U5] Register view issue after RDP1 password set/disable.
132716	[Documentation] UM2237 Rev 19: Incorrect description of I2C configuration panel.
133012	[GUI][STM32U5] Wrong number of sectors for 1-Mbyte device.
133019	[STM32CubePRG][ST-LINK] STM32CubeProgrammer keeps reading BL version and displays it in VB3 every second.
133020	[STM32CubeProg][STM32L0][GUI] BL version is not displayed.
133242	[API][USB] Cannot list USB_DFU with custom VID&PID.
134250	[Documentation][UM2237] Add explanation for <code>-startstack</code> .
134536	[STM32CubeProg][TPC] “Generate Hash” option must be checked by default.
134843	[Documentation][UM2238] TPC wrong example for area 'K' pairs.
135228	[SFI] Update option bytes notation in CSV files.
135237	[STM32CubeProg][CLI] Update of Inventek Wi-Fi® firmware fails on B-L475E-IOT01 and B-L4S5I-IOT01 boards.
135272	[STM32CubeProg][STM32U5] Wrong flash memory sector size for STM32U575ZI (2 Mbytes).
135805	[API] Update <code>getExternalLoader</code> parameter description to match current implementation.
136171	[STM32CubeProg - Documentation][AN5054] Confusing “multi install” expression in secure programming using STM32CubeProgrammer application note.
137358	[STM32G4] Erase selected sectors does not work properly on devices with 256 Kbytes of flash memory.

### 3.7.3 Known problems and limitations

- Integrity check:
  - STM32H7 microcontrollers: support integrity check for SFI/SMI:
    - Only the devices with a bootloader version higher than 0x91 are supported.
    - STM32CubeProgrammer v2.12.0 does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
  - STM32H73xxx microcontrollers: support integrity check for SFI/SMI/SFIx:
    - Only the devices with a bootloader version higher than 0x93 are supported.
    - STM32CubeProgrammer v2.12.0 does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
  - STM32H7Bxxx microcontrollers: support integrity check for SFI/SMI/SFIx:
    - Only the devices with a bootloader version higher than 0x92 are supported.
    - STM32CubeProgrammer v2.12.0 does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
- Command-line interface:
  - Shared devices listing issue with the `-l` option.
  - Missing data from the `.hex` file when using `safelib`.
- Graphical user interface:
  - Missing data from the `.hex` file when using `save to file`.
- Auto mode (Linux® platform):
  - The SPI interface quits after starting without a connection.
- STM32G0 microcontrollers:
  - The `.hex` file does not modify the WRP and PCROP option bytes of bank 2 for the devices with 512 Kbytes of dual-bank flash memory.
  - The SWD `RegDump` command-line instruction does not work on STM32G081xx devices.
- STM32H7 microcontrollers:
  - STM32CubeProgrammer does not support combined SFI and SMI.
  - SMI programming fails.
- STM32L4 microcontrollers:
  - The full chip erase fails in SPI mode for devices with 1 Mbyte of flash memory.
- STM32L4+ microcontrollers:
  - It is not possible to write the WRP1B and WRP2B option bytes for devices with 2 Mbytes of flash memory.
- STM32MP15x microprocessors:
  - It is not possible to program a `.tsv` file when some partitions are not selected.
  - An error occurs when saving the OTP partition in a macOS® platform.
- STM32U5 microcontrollers:
  - RDP regression with password is not working on macOS®.
  - It is impossible to set OEM keys through DFU.
- STM32WB1xxx microcontrollers:
  - The register dump command is not supported.
- Azure® RTOS USBX:
  - For STM32U575/585 microcontrollers, erasing sectors from "C" to "F" fails.
  - For STM32U575/585 microcontrollers, some extra data is added at memory programming.
  - For STM32F4 microcontrollers, rewriting at a same memory address fails.

## 3.8 STM32CubeProgrammer v2.11.0 release information

### 3.8.1 New features

- Tool updater: can be used to upgrade [STM32CubeProg](#) from v2.10.0 to v2.11.0 for all supported operating systems (Windows®, Linux®, and macOS®)
- SFI:
  - SFIx support for STM32U585xx microcontrollers via SWD/JTAG
  - New SFI/SFIx graphical user interface (GUI)
  - STM32 Trusted Package Creator SFI GUI enhancement
  - Support for integrity check with the [STM32H7 series](#) and [STM32U5 series](#) microcontrollers
- [STM32U5 series](#): the GUI supports the RDP regression with password
- New bootloader support for STM32L476xx microcontrollers
- STM32MP13xx microprocessors:
  - Flash memory load via USB-DFU/UART
  - SSP (command-line interface only)
  - OTP: CLI/GUI

### 3.8.2 Fixed issues

**Table 9. Main issues fixed in STM32CubeProgrammer v2.11.0**

ID	Summary
90858	[STM32WB][CLI] Optimize FUS, STACK, and USER app upgrading automatically.
104409	STM32H735xx: SFI is very slow over SWD.
109240	Extra option bytes displayed for STM32G030C6: PCROP1A_STRT, PCROP1A_END, PCROP1A_RDP, PCROP1B_STRT, PCROP1B_END, and BOOT_LOCK, SEC_SIZE.
110205	Fix the reading of CHIPID (DBGMCU_DBG_AUTH_DEVICE) on STM32U5 microcontrollers.
110614	[CLI] Error level not reported correctly for the CRC safety feature using STM32CubeProgrammer_CLI.
117163	Launch problem when running the STM32CubeProgrammer GUI from another path.
119604	[STM32G0][OB] Sector erase cannot be achieved and an STM32CubeIDE debug error occurs when nSWAP_BANK=0.
120935	STPC v2.9 cannot generate a correct .sfi file for SFI.
121452	[OB] Incorrect SRAM2b secure address for STM32WB1xxx.
121713	Typo: “Memory & file edition”.
123018	[STM32H7][CM4] BOOT_CM4_ADD cannot be modified.
123740	[DFU] The single-bank configuration is not correctly managed when connecting with DFU.
123913	[CLI] It is not possible to write the LOCK byte.
123923	[UART] A timeout error occurs while disabling the readout protection.
124081	Odd behavior in the log when connecting a NUCLEO-F030R8 using the GUI.
124446	Request to add documentation for the <code>getAuthID</code> command.
124763	[OB] Wrong description of nBOOT1.
125039	[DFU] Strange behavior when trying to program in single-bank mode.
127099	[STM32L4+] Fail to program STM32L4+ twice in a row.
127311	The tool closes automatically when trying to load a file the path of which contains Chinese characters.
127978	Typo in option bytes: IWGDSTDBY.

### 3.8.3 Known problems and limitations

- No error message is displayed when the microcontroller is not powered.
- A segmentation fault occurs when the STM32CubeProgrammer CLI is executed with a wrong serial number.
- Integrity check:
  - STM32H7 microcontrollers: support integrity check for SFI/SMI:
    - Only the devices with a bootloader version higher than 0x91 are supported.
    - STM32CubeProgrammer v2.11.0 does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
  - STM32H73xxx microcontrollers: support integrity check for SFI/SMI/SFIx:
    - Only the devices with a bootloader version higher than 0x93 are supported.
    - STM32CubeProgrammer v2.11.0 does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
  - STM32H7Bxxx microcontrollers: support integrity check for SFI/SMI/SFIx:
    - Only the devices with a bootloader version higher than 0x92 are supported.
    - STM32CubeProgrammer v2.11.0 does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
- STM32H7 microcontrollers:
  - STM32CubeProgrammer does not support combined SFI and SMI.
  - The Cortex<sup>®</sup>-M4 boot address for dual-core STM32H7 microcontrollers is not modified with the SWD interface.
- STM32U5 microcontrollers:
  - RDP regression with password is not working on macOS<sup>®</sup>.
  - SFIx is not working for bootloader interfaces.
  - An RSS CMD error is returned on area C during SFI.
  - An incorrect RSSe version is displayed.
  - The SFI process is successful while generating errors.
  - RDP2 and BootLock fail to be programmed in one shot over SWD.
  - The SFI installation process ends with a segmentation fault (Linux<sup>®</sup>/macOS<sup>®</sup>).
- STM32G0 microcontrollers:
  - Extra data is added during OTP programming in DFU.
  - STM32G0B0xx device is missing from the device list with ID 0x467.
- STM32WB1xxx microcontrollers:
  - The register dump command is not supported.
- Azure<sup>®</sup> RTOS USBX:
  - For STM32U575/585 microcontrollers, erasing sectors from "C" to "F" fails.
  - For STM32U575/585 microcontrollers, some extra data is added at memory programming.
  - For STM32F4 microcontrollers, rewriting at a same memory address fails.

## 3.9 STM32CubeProgrammer v2.10.0 release information

### 3.9.1 New features

- Added the updater tool for automatic software updates.  
The updater allows the users to make automatic updates of the software and its associated packages. It is available in all supported operating systems: Windows<sup>®</sup>, Linux<sup>®</sup>, and macOS<sup>®</sup>.
- Added the support for OpenBootloader via UART for the [STM32U5 series](#).
- Added the possibility to unlock the STM32WL dual-core microcontrollers after a wrong option byte programming through a new button in the GUI or a command in the CLI.
- Added the support for the STM32U59x/5Ax microcontrollers.
- Added the SFI, SMI, and SFIx integrity check for the STM32H73xxx microcontrollers.

### 3.9.2 Fixed issues

**Table 10. Main issues fixed in STM32CubeProgrammer v2.10.0**

ID	Summary
82999	[STM32WB series] Make feature, RF Stack type, and version visible on GUI.
83752	Inconsistent use of bin option for STM32MP1 microprocessors.
97890	Integrate the modified MT25TL01G_STM32H750B-DISCO.stldr.
102454	Add spent time information for option byte configuration in log file.
103609	[Signing_Tool] Allow the change of the <code>-of</code> option on an already signed stm32 file.
108742	[STM32L151RD] Wrong flash memory size: 128 Kbytes instead of 384 Kbytes.
111228	Add <i>Check for updates</i> feature.
112974	STM32MPU157F-EV1 Android™ OS flash programming problem.
113279	Confusing behavior with NUCLEO-U575ZI-Q at 1.8 V with the SWD frequency max.
116342	Add the support of <code>.s19</code> files.
118242	STM32CubeProgrammer fails to program an image bigger than 2.8 Kbytes and shows a wrong image size.
118288	OpenBootloader via SPI receives a checksum as flash memory page number in <code>Erase Memory</code> command from STM32CubeProgrammer.
118871	[FlashLoader] Update the external flash loader <code>0x450.stldr</code> .
119243	[STM32G0 series][GUI] Wrong RAM_PARITY_CHECK description.
119940	RDU fails on STM32G071xx with RDP set to BB and active bootlock on last cut.
120160	<code>nRST_STOP</code> , <code>nRST_STDBY</code> , and <code>nRST_SHDW</code> option byte values are modified when scrolling the user configuration option bytes TAB.
120954	The <code>.bin</code> file cannot be programmed successfully on STM32L4R9xx microcontrollers.
121620	TFA decryption fails.

### 3.9.3 Known problems and limitations

- SFI, SMI, and SFIx integrity check for the STM32H73xxx microcontrollers:
  - Only the devices with a bootloader version higher than 0x93 are supported.
  - STM32CubeProgrammer v2.10.0 does not support the devices with older bootloader versions. Users must use STM32CubeProgrammer v2.9.0 to use devices with old bootloader versions.
  - Users who want to use SFI on STM32H75xxx and STM32H7Bxxx must use STM32CubeProgrammer v2.9.0 because of the broken compatibility with the integrity check mechanism.
  - Refer to the application note [AN5054](#) for details.
- STM32CubeProgrammer does not support combined SFI and SMI for STM32H7 microcontrollers.
- Azure® RTOS USBX:
  - For STM32U575/585 microcontrollers, erasing sectors from "C" to "F" fails.
  - For STM32U575/585 microcontrollers, some extra data is added at memory programming.
  - For STM32F4 microcontrollers, rewriting at a same memory address fails.
- STM32 Trusted Package Creator on macOS® fails to detect the HSM card reader.
- STM32 Trusted Package Creator on Linux® does not detect HSM only when the TPC CLI is launched in `sudo` mode.
- STM32WB55xx microcontrollers / FUS\_StackWB: After key update, the progress bar remains red even after the programming ended successfully.
- Address is always equal to 0x0 when saving a binary as `.hex` file.
- STM32CubeProgrammer fails to program any option byte or memory when `WWDG_SW` (or `IWDG_SW`) is unchecked.

## 3.10 STM32CubeProgrammer v2.9.0 release information

### 3.10.1 New features

- Updated the programming mechanism for the STM32U575/585 microcontrollers via a flash loader usage in TZEN = 0, and a new programming mode in TZEN = 1 (fast/reliable)
- Added double authentication and user keys provisioning via JTAG for the [STM32WB series](#) (feature only available with bootloader in previous versions)
- Added a scripting mode including the existing STM32CubeProgrammer CLI commands and a new macro for data manipulation
- Added the support for the PKCS#11 protocol in the signing tool ([STM32MP1 series](#)).
- Added the support for Microsoft® Azure® RTOS USBX DFU stack

### 3.10.2 Fixed issues

**Table 11. Main issues fixed in STM32CubeProgrammer v2.9.0**

ID	Summary
110368	STM32L5 RSSe binary must be renamed as it handles both the JTAG and bootloader.
110531	[FUS] Upgrade problem with STM32CubeProgrammer of <code>stm32wb5x_FUS_fw.bin</code> version v1.2.0 on STM32WB55RE (512 Kbytes).
111044	Programming issue using STM32L486xx microcontrollers connected via USB.
111417	Changing secure area errors.
112266	Debug in Low-power mode does not display the right state of Stop bit.
112484	New ST-LINK firmware release V3J8M3 should limit bandwidth to 1 MHz on GUI.
112545	CLI does not read all requested upload sizes.
113605	[CLI] Erase all not possible using UART.
113806	[OB] Error message when configuring WRP option byte.
114171	STM32CubeProgrammer fails to program large segmented <code>.hex</code> file to external flash memory.
114893	[STM32G4] Bit SEC_SIZE1[8] cannot be programmed.
115651	Issue with option bytes IWDG and WWDG for STM32G07xxx devices.
116070	Programmer failed to load bin on STM32U5 with newer ST-LINK firmware version.

### 3.10.3 Known problems and limitations

- *Script Manager* on Linux®: STM32CubeProgrammer does not recognize a `.prg` file when the directory name contains capital letters.
- STM32 Trusted Package Creator on macOS® fails to detect the HSM card reader.
- STM32 Trusted Package Creator on Linux® does not detect HSM only when the TPC CLI is launched in `sudo` mode.
- STM32WB55xx microcontrollers / FUS\_StackWB: After key update, the progress bar remains red even after the programming ended successfully.
- Address is always equal to 0x0 when saving a binary as `.hex` file.
- STM32CubeProgrammer fails to program any option byte or memory when WWDG\_SW (or IWDG\_SW) is unchecked.
- [STM32L151RD](#): wrong flash memory size displayed (128 Kbytes instead of 384 Kbytes).

## 3.11 STM32CubeProgrammer v2.8.0 release information

### 3.11.1 New features

- Added the support for the STM32U575/585 microcontrollers



- Added the support for SFI via the JTAG interface for the STM32U575/585 microcontrollers
- Added the support for SFI via the bootloader interface (USB/UART/I<sup>2</sup>C/SPI) for the STM32U5 series
- Added the new *FUS-Operator* support for the STM32WB1xxx microcontrollers
- Added the anti-rollback support for the STM32WB1xxx and STM32WB5xxx microcontrollers
- Added the support of FUS version display for the STM32WB1xxx and STM32WB5xxx microcontrollers
- Added the support for the *Live Grid Update* feature
- Added the support for the *Blank check* feature
- Added the support for the *Memory/File* and *File/File* compare features
- Added the support for the bootloader version display feature
- Added the support for the *Fill memory* feature
- Added the support for UART interface RTS/CTS signals
- Added the support for *Connect while Watchdog enabled*

### 3.11.2 Fixed issues

**Table 12. Main issues fixed in STM32CubeProgrammer v2.8.0**

ID	Summary
64267	Fix issues with FUS via USART boot mode.
72832	Fix issue with MCU ID for STM32L151VB and STM32L151CB.
74327	[STM32F7] Unable to read/write data when option byte WWDG_SW is unchecked.
76440	[STM32WB] Extra bytes are programmed.
81646	STM32G431RB WRP modification.
93987	[STM32G0][GUI] Remove NRST_MODE.
100150	Programming of option bytes list is not completed when SEC_SIZE option byte is programmed.
101017	[STM32H7] Completes data with 00 bytes at the end.
102103	[STM32G0] Bit field for BORR and BORF are swapped.
104089	[STM32G0] Only half of the flash memory is shown under “Erase & Programming”, and missing DUAL_BANK and (n)SWAP_BANK option bytes for STM32G0[B-C][0-1]xE microcontrollers.
104320	[STM32WB] The stack “Firmware delete” button is greyed out when connected through USB DFU.
104707	[STM32U5] RDP regression is not possible when IWDG_SW/WWDG_SW option byte is set to 1.
104832	[STM32G0] NRST_MODE option byte has been removed for STM32G0x1xx microcontrollers.
105628	[STM32U5] HDP option byte is not visible.

### 3.11.3 Known problems and limitations

- **STM32G030C6**: extra option bytes displayed (PCROP1A\_STRT, PCROP1A\_END, PCROP1A\_RDP, PCROP1B\_STRT, PCROP1B\_END, BOOT\_LOCK, SEC\_SIZE)
- **STM32L151RD**: wrong flash memory size displayed (128 Kbytes instead of 384 Kbytes)
- **STM32U575/585** microcontrollers:
  - Bootloader version is not displayed
  - SFI via SWD fails when a USB cable is connected (a workaround is to use a USB wall charger)
  - On macOS®, after setting RDP to 0x55 and TZEN to 0x1, a connection via SWD crashes the tool
  - Regression with PWD from L1 to L0.5 fails
- STM32 Trusted Package Creator tool: HSM cannot be detected on macOS®
- Frequency parameters are not respected
- Azure® RTOS USBX is not supported

## 3.12 STM32CubeProgrammer v2.7.0 release information

### 3.12.1 New features

- Added the support for the STM32WB15xx microcontrollers in the [STM32WB series](#)
- Added the support for the microcontrollers with 64 Kbytes of flash memory in the [STM32G0 series](#)
- Added *HardFault Analyzer* support
- Added *Register viewer* support

### 3.12.2 Fixed issues

**Table 13. Main issues fixed in STM32CubeProgrammer v2.7.0**

ID	Summary
58716	Error when trying to mass erase STM32L0 128K devices from the CLI.
61638	DFU error with the STM32F746xx microcontrollers.
64229	Impossible to erase sector 128 and upper on STM32L476RG with STM32CubeProgrammer.
73928	[STM32CubeProgrammer][CLI][STM32H7] STM32H745I-DISCO: Unable to read big data from the external Q-SPI flash memory.
78496	STM32F756 DFU <i>Application Example</i> does not work with STM32CubeProgrammer.
80586	[STM32CubeProgrammer][STM32L0][CLI] Verification progress bar ends at 24%.
85736	Empty area in HEX file is not well detected by STM32CubeProgrammer.
85898	Option byte IRHEN must be deleted from STM32CubeProgrammer.
89140	[STM32CubeProgrammer v2.4.0][CLI]: Failure to recover when using the <code>rd</code> option.
90060	[STM32L4] STM32L496: Cannot connect using DFU IAP.
91608	Programming issue using the NUCLEO-L053R8 board connected via the USB.
92200	[CLI] J <sup>2</sup> C Host sends out 2 extra bytes in the <code>NoStretchErase</code> command.
92774	[UART] STM32CubeProgrammer cannot program STM32H7 microcontrollers between 0x0810 0040 and 0x0810 0800.
93858	STM32H757 bootloader UART - <code>.hex</code> download verify error on the Cortex <sup>®</sup> -M4.
93887	STM32F765xG (1 Mbyte): Not possible to program the flash memory using STM32CubeProgrammer v2.5.0.
94636	[STM32CubeProgrammer-IAP] DFU programming failed.
96040	[GUI] When " <i>No STM32 target found</i> " STM32CubeProgrammer cannot be closed.
96295	STM32L471: Not able to successfully connect to or program using the UART.
96905	[Prg-DB] Wrong flash memory size for STM32L151xx devices.
97365	USB DFU connection issue using the NUCLEO-L152RE board.
98346	STM32L073: STM32CubeProgrammer v2.6.0 is not able to successfully connect to STM32L073xx microcontrollers using DFU.
98682	Programming issues using STM32L471VET6.
99401	[STM32G4 128K][GUI] Wrong WRP1A/B_END and WRP1A/B_STRT values for 128 Kbytes.
99963	STM32CubeProgrammer_API document update for STM32MP1 microprocessors.

### 3.12.3 Known problems and limitations

- Installer: Insignificant message is returned during the installation when other instances are already installed.
- On some macOS<sup>®</sup> machines, the STM32CubeProgrammer GUI fails to launch (must be launched in CLI mode).

- STM32WB1xxx: Incorrect PCROP area management via SWD.
- STM32WB1xxx: STM32CubeProgrammer is closed when trying to apply FUS upgrade via the UART on macOS®. Only tty is supported.
- STM32WB5xxx: Making FUS upgrade via the SWD interface from recent to older version returns success message.
- Programming of option byte list is not completed when the SEC\_SIZE option byte is programmed on some STM32 microcontroller or microprocessor series.
- STM32WB1xxx: STM32Key Provisioning/Double signature is not tested.

### 3.13 STM32CubeProgrammer v2.6.0 release information

#### 3.13.1 New features

- Added the support for dual-core microcontrollers in the STM32WL series
- Extended the support for the STM32G0 series to the new STM32G0Bxxx and STM32G0Cxxx microcontrollers
- Added SFI support via JTAG/UART/SPI for STM32WL5xxx microcontrollers
- Added SFI support via I<sup>2</sup>C/SPI for STM32L5 series microcontrollers
- Added SFIx support via bootloader for STM32L5 series microcontrollers
- Added Sigfox™ credential provisioning support for STM32WL5xxx microcontrollers
- Added multiple flash loader support for STM32 microcontrollers
- Added the SWV feature update (color support)
- Added the support for the server client HSM feature
- Added DFU IAP using custom PID/VID support for all STM32 products
- Added installer JRE bundle (OpenJDK)

#### 3.13.2 Fixed issues

**Table 14. Main issues fixed in STM32CubeProgrammer v2.6.0**

ID	Summary
57835	Connect under reset with hardware reset is not working with SensorTile in low-power mode.
58716	Error when trying to mass erase STM32L0 128-Kbyte devices from CLI.
62639	RDP regression is not functional via BootLoader interfaces for STM32F030R8.
64267	Issues with FUS via USART boot mode.
70556	[STM32CubeProgrammer] Bug with STM32F7651GT6 (1-Mbyte flash memory).
76987	[STM32CubeProg-STM32L5] STM32Cubeprog crash when communicating with the DFU app.
80586	[STM32CubeProg-STM32L0][CLI] Verification progress bar ends at 24%.
81647	User DFU functionality with STM32CubeProgrammer.
85313	[STM32CubeProg-STM32G0][GUI] Remove the BOR level section.
85898	Option Byte IRHEN must be deleted from STM32CubeProgrammer.
85960	STM32G431: STM32CubeProgrammer automatic mode download issue.
86576	[PRG] Fail to write OTP with STM32G4.
90060	[STM32CubeProgrammer][STM32L4] STM32L496: cannot connect using DFU IAP.
91608	Programming issue using the NUCLEO-L053R8 board connected via USB.
92038	STM32CubeProgrammer fails to open on macOS® Catalina v 10.15.6.
92280	[STM32CubeProg-STM32H7][GUI] Erasing & Programming panel hangs (white panel).
92477	[STM32CubeProg-STM32L1][GUI] Incorrect memory size displayed and cannot make the erase.

ID	Summary
92641	[STM32CubeProgrammer-Option Bytes] Cannot set STM32H743 IO_HSLV, VDDIO_HSLV option bit.
92674	[STM32CubePrg][STM32L0][DIE417] Cannot connect to board under reset when low-power mode is activated.
92828	Seems no compatible OpenJFX version for Ubuntu® 20.04 for OpenSTLinux.
93013	[CubePRG] CubeProgrammer_API.h not up to date in last STM32CubeProgrammer: missing 100 bytes in debugConnectParameters struct.
93887	[CubePRG][0x451] Not possible to program STM32F765xG (flash 1 Mbyte) using STM32CubeProgrammer v2.5.0.
93987	[STM32CubeProg-STM32G0][GUI] Remove NRST_MODE.
94517	[CubePRG] Cannot write 8 bytes in flash memory using <code>-w64</code> STM32CubeProgrammer CLI command.

### 3.13.3 Known problems and limitations

- STM32MP1 microprocessor `get_certificate` operation is not complete in the UART mode.
- Production programming issues occur when using multiple ST-LINK in parallel.
- Installer: Insignificant message is returned during the installation when other instances are already installed.
- On some macOS® machines, the STM32CubeProgrammer GUI fails to launch (must be launched in CLI mode).
- The SFI operation via UART is not achieved and returns an error on macOS® machines.
- STM32WB55: When trying to upgrade more than one stack, the operation can be done only with a second try.
- SFlx operation for STM32L5: An exception appears while programming when the `-e1b1` command is not the first one in the command line.

## 3.14 STM32CubeProgrammer v2.5.0 release information

### 3.14.1 New features

- Added the support for STM32G491xC and STM32G491xE microcontrollers
- Added the support for STM32H72xxx and STM32H73xxx microcontrollers
- Added SFI support for STM32H72xxx and STM32H73xxx microcontrollers
- Added SFlx support for STM32H72xxx and STM32H73xxx microcontrollers
- Added SFI support via UART for STM32L5 series microcontrollers
- Added SFI support via USB for STM32L5 series microcontrollers
- Added support of Serial Wire Viewer (SWV)
- Board automatic recognition
- Revision ID display

### 3.14.2 Fixed issues

**Table 15. Main issues fixed in STM32CubeProgrammer v2.5.0**

ID	Summary
59191	[STM32WB] Unable to remove or install the RF stack over UART bootloader + RSS.
60618	Erase of EEPROM memory of STM32L051 using the <i>Erase selected sectors</i> option.
62173	Cannot connect to STM32F072 DFU system bootloader.
65682	[UART] Cannot update option bytes with the UART.
66596	[UART] STM32L010 can be programmed.

ID	Summary
67646	CLI missing <code>-w64</code> command + OTP area not programmed via SWD.
68736	[STM32F7] Unable to erase multiple sectors for dual-bank flash memory.
68990	[secure boot] Key generation not functional with <code>STM32MP_KeyGen_CLI</code> on Linux®.
70592	Start address box is activated after programming <code>.hex</code> file.
71108	[STM32H7] Flash programming through SWD in SFI mode finishes with errors.
73495	[STM32F072] Cannot remove read protection through DFU bootloader.
79494	Fail to program STM32L0 MCUs
79912	[STM32F446] Flash memory size register reading with bootloader interface.
82752	[UART][CLI] Upload size is bigger than flash memory size.
82867	<i>Firmware Upgrade Service</i> panel does not disappear on disconnect from compatible device.
83296	[STM32L5][SFI]: SFI fails if RDP is set to 0 or 1 in <code>.csv</code> file or if start SFI with <code>TZEN=1</code> .
83346	<code>GetCubeprogrammer_API.lib</code> compiled with x64.
88504	Issues with programming 512-Kbyte memory with 362-Kbyte file.
89436	Failure to program binary to STM32L4 Nucleo board with the CAN interface using bootloader.

### 3.14.3 Known problems and limitations

- For the STM32L5 series, the Option Byte programming GUI is not intuitive enough. Refer to the *STM32L552xx and STM32L562xx advanced Arm®-based 32-bit MCUs* reference manual (RM0438) for permitted accesses.
- For STM32L4Pxxx and STM32L4Qxxx devices, Option Byte programming via bootloader interfaces presents some limitations.
- For STM32H7Axxx and STM32H7Bxxx devices, Option Byte programming via bootloader interfaces (USB) presents some limitations.
- STM32L5 series programming presents limitation in macOS® when `TZEN=1` and `rdp=0x55`.
- Display issues depending on the monitor used can occur with Linux®.
- SFI-HSM V2 *get certificate* fails with STM32L462xx devices.
- Parallel flash programming fails in macOS® for microprocessors in the STM32MP1 series.
- Issues can be reported with some specific `.elf` file in CRC calculation safety feature.
- STM32MP1 microprocessor programming via UART presents limitations to program the whole boot chain.
- STM32MP1 microprocessor *get certificate* operation is not completed via a UART connection.

## 3.15 STM32CubeProgrammer v2.4.0 release information

### 3.15.1 New features

- Added the support of the graphic user interface (GUI) for the firmware upgrade service (FUS) and stack upgrade for the entire STM32WB series
- Support of HSM V2 on all STM32 microcontrollers and microprocessors supporting SFI/SSP

### 3.15.2 Fixed issues

**Table 16. Main issues fixed in STM32CubeProgrammer v2.4.0**

ID	Summary
77015	STM32CubeProgrammer cannot connect ST-LINK without the mass storage feature.
78350	STM32CubeProgrammer issue with STM32G0 when programming binary (size 18448 bytes).

### 3.15.3 Known problems and limitations

- For the STM32L5 series, the connection via the ST-LINK protocol is allowed only when mode is set to *hotplug* with `TZEN=1`.
- For the STM32L5 series, the Option Byte programming GUI is not intuitive enough. Refer to the *STM32L552xx and STM32L562xx advanced Arm®-based 32-bit MCUs* reference manual (RM0438) for permitted accesses.
- For STM32L4Pxxx and STM32L4Qxxx devices, Option Byte programming via bootloader interfaces presents some limitations.
- For STM32H7Axxx and STM32H7Bxxx devices, Option Byte programming via bootloader interfaces (USB) presents some limitations.
- STM32L5 series programming presents limitation in macOS® when `TZEN=1` and `RDP=0x55`.
- With some small-screen resolutions, the graphical interface of STM32CubeProgrammer presents anomalies such as inaccessible buttons.
- Display issues depending on the monitor used can occur with Linux®.
- SFlx on STM32H743/753 devices fails via the debug interface.
- SFI-HSM V2 *get certificate* fails with STM32L462xx devices.
- Parallel flash programming fails in macOS® for microprocessors in the STM32MP1 series.

## 3.16 STM32CubeProgrammer v2.3.0 release information

### 3.16.1 New features

- Added the support of the STM32L4Pxxx and STM32L4Qxxx microcontrollers
- Added the support of the STM32H7Axxx and STM32H7Bxxx microcontrollers
- Added the beta support of the STM32WL series microcontrollers
- Added the official support of the STM32L5 series microcontrollers
- Added the support of HSM V1 SFI/SFlx for STM32H7Axxx microcontrollers
- Added the support of HSM V1 SFI/SFlx for STM32L5 series microcontrollers

### 3.16.2 Fixed issues

**Table 17. Main issues fixed in STM32CubeProgrammer v2.3.0**

ID	Summary
63887	STM32CubeProgrammer does not program Option Byte from an <code>.hex</code> file for STM32F446xx.
64229	STM32Cubeprogrammer does not erase sector 128 and upper on STM32L476RG.
66609	STM32CubeProgrammer programming request of OTP byte via STM32CubeProgrammer.
67025	STM32Cubeprogrammer cannot connect ST-LINK without the mass storage feature.
77015	Support flash loader for STM32F769-EVAL:MT25QL512.

### 3.16.3 Known problems and limitations

- For the STM32L5 series, the connection via the ST-LINK protocol is allowed only when mode is set to *hotplug* with `TZEN=1`.
- For the STM32L5 series, the Option Byte programming GUI is not intuitive enough. Refer to the *STM32L552xx and STM32L562xx advanced Arm®-based 32-bit MCUs* reference manual (RM0438) for permitted accesses.
- For STM32L4Pxxx and STM32L4Qxxx devices, Option Byte programming via bootloader interfaces presents some limitations.
- For STM32H7Axxx and STM32H7Bxxx devices, Option Byte programming via bootloader interfaces (USB) presents some limitations.

- STM32L5 series programming presents limitation in macOS® when TZEN=1 and RDP=0x55.
- With some small-screen resolutions, the graphical interface of STM32CubeProgrammer presents anomalies such as inaccessible buttons.
- Display issues depending on the monitor used can occur with Linux®.

## 3.17 STM32CubeProgrammer v2.2.1 release information

### 3.17.1 New features

No new feature is reported for this release. Minor release v2.2.1 is dedicated to issue correction (refer to [Fixed issues](#)).

### 3.17.2 Fixed issues

**Table 18. Main issue fixed in STM32CubeProgrammer v2.2.1**

ID	Summary
74031	STM32CubeProgrammer issue programming STM32H7 Rev V via DFU.

### 3.17.3 Known problems and limitations

- For the STM32L5 series, the connection via the ST-LINK protocol is allowed only when mode is set to *hotplug*.
- For the STM32L5 series, the Option Byte programming GUI is not intuitive enough. Refer to the *STM32L552xx and STM32L562xx advanced Arm®-based 32-bit MCUs* reference manual (RM0438) for permitted accesses.
- For the STM32L5 series, Option Byte programming via bootloader interfaces presents some limitations.
- STM32CubeProgrammer does not work under Ubuntu® 18.04.
- With some small-screen resolutions, the graphical interface of STM32CubeProgrammer presents anomalies such as inaccessible buttons.
- Display issues depending on the monitor used can occur with Linux®.

## 3.18 STM32CubeProgrammer v2.2.0 release information

### 3.18.1 New features

- Added the support of the STM32L5 series
- Added the support of HSMv2
- Added the support of IAP for the USB-DFU interface
- STM32WB firmware upgrade via the ST-LINK interface
- Added the support of OTP for the STM32L5 series
- Added the support of SSP for the STM32MP1 series

### 3.18.2 Fixed issues

**Table 19. Main issues fixed in STM32CubeProgrammer v2.2.0**

ID	Summary
58587	STM32CubeProgrammer does not support STM32L433RC-P and STM32L433RB.
61375	STM32L073 - How to erase the Data EEPROM?
61731	CLI Device not supported but programmed. RDP not programmed.
68802	USB DFU for STM32L452 and STM32L476 device IDs is unknown while connecting with the USB.

ID	Summary
68916	STM32CubeProgrammer does not recognize STM32F413 USB DFU.
69927	IAP DFU is not working with STM32CubeProgrammer: <code>Error Unknown</code> or unsupported device (DevID = 0x0000).
71074	STM32CubeProgrammer v2.1.0 defect - DFU mode sector erase fails on STM32H743 2MB Rev V.

### 3.18.3 Known problems and limitations

- For the STM32L5 series, the connection via the ST-LINK protocol is allowed only when mode is set to *hotplug*.
- For the STM32L5 series, the Option Byte programming GUI is not intuitive enough. Refer to the *STM32L552xx and STM32L562xx advanced Arm®-based 32-bit MCUs* reference manual (RM0438) for permitted accesses.
- For the STM32L5 series, Option Byte programming via bootloader interfaces presents some limitations.
- STM32CubeProgrammer does not work under Ubuntu® 18.04.
- With some small-screen resolutions, the graphical interface of STM32CubeProgrammer presents anomalies such as inaccessible buttons.

## 3.19 STM32CubeProgrammer v2.1.0 release information

### 3.19.1 New features

- Added support of STM32G4 series
- Added support of STM32G03x/STM32G04x microcontrollers
- Added support of dual-core microcontrollers in the STM32H7 series
- Added support of secure firmware install (SFI)

### 3.19.2 Fixed issues

**Table 20. Main issues fixed in STM32CubeProgrammer v2.1.0**

ID	Summary
62057	Download file is always executed after simple download with ST-LINK/V2 and STLINK-V3.
64155	Impossible to erase sector 128 and upper on STM32L476RG with STM32CubeProgrammer.

### 3.19.3 Known problems and limitations

- The use of the UART bootloader prevents from increasing the RDP level and programming the second bank of Option Bytes, or from enabling the two user secure areas simultaneously on STM32H7 microcontrollers.
- Programming over USB bootloader is not reliable with USB2.0 for some devices.
- External memory programming is only available with ST-LINK.
- Installing multiple instances of the same version of the tool in the same directory under Windows® leads to issues when uninstalling.
- UART flash programming of devices in the STM32MP1 series may fail with big partitions.
- Programming issues are observed with the STM32H7 series when the STLINK-V3 I<sup>2</sup>C interface is used.
- GUI issues are sometimes observed with the OTA programming of devices in the STM32WB Series.
- Linux® 32 bits is not supported.
- STM32 Trusted Package Creator: only the CLI version is supported on macOS®.
- Mass Erase is not working with the SPI bootloader interface on the STM32WB series.



- Mass Erase is not working with the I<sup>2</sup>C bootloader interface on the STM32G4 series; errors can occur when writing via the SPI interface.
- Shared mode: board detection failure is observed after multiple refresh operations.
- Writing 8-bit data in RAM on STM32L496G devices is not possible.

## 3.20 STM32CubeProgrammer v2.0.0 release information

### 3.20.1 New features

- Added support of STM32MP1 series
- Added support of STM32WB series
- Added support of *Automatic Mode* for programming devices in a loop
- Added support of OTA programming for the STM32WB series

### 3.20.2 Fixed issues

**Table 21. Main issues fixed in STM32CubeProgrammer v2.0.0**

ID	Summary
58879	Internal flash programming issue with <a href="#">STM32L433RC</a> (SMPS version) and <a href="#">STM32L433RB</a> .
60257	<i>stlinkv3.rules</i> is missing in the <i>drivers\rules\</i> folder.

### 3.20.3 Known problems and limitations

- The use of the UART bootloader prevents from increasing the RDP level and programming the second bank of Option Bytes, or from enabling the two user secure areas simultaneously on STM32H7 microcontrollers.
- Programming over USB bootloader is not reliable with USB2.0 for some devices.
- External memory programming is only available with ST-LINK.
- Installing multiple instances of the same version of the tool in the same directory under Windows<sup>®</sup> leads to issues when uninstalling.
- UART flash programming of devices in the STM32MP1 series may fail with big partitions.
- Programming issues are observed with the STM32H7 series when the STLINK-V3 I<sup>2</sup>C interface is used.
- GUI issues are sometimes observed with STM32WB series OTA programming.
- Linux<sup>®</sup> 32 bits is not covered.
- STM32 Trusted Package Creator: only the CLI version is supported on macOS<sup>®</sup>.

## 3.21 STM32CubeProgrammer v1.4.0 release information

### 3.21.1 New features

- Added STM32CubeProgrammer C++ API
- Added support of secure firmware install on [STM32L462CEU6F](#)

### 3.21.2 Fixed issues

**Table 22. Main issues fixed in STM32CubeProgrammer v1.4.0**

ID	Summary
55454	Programming a STM32F765NIH6 via USART1 can be done.
56817	Cannot program internal flash memory of STM32F722ZE and STM32F730R8 via USB.

### 3.21.3 Known problems and limitations

- Read/write operations fail with the CAN interface.
- The use of the UART bootloader prevents from increasing the RDP level and programming the second bank of Option Bytes, or from enabling the two user secure areas simultaneously on STM32H7 microcontrollers.
- Programming over USB bootloader is not reliable with USB2.0 for some devices.
- External memory programming is only available with ST-LINK.
- Installing multiple instances of the same version of the tool in the same directory under Windows® leads to issues when uninstalling.
- The STLinkV3-I2C bridge may not work correctly with STM32F4 series, STM32F7 series, and STM32H7 series.

## 3.22 STM32CubeProgrammer v1.3.0 release information

### 3.22.1 New features

- Added support of STM32G07x and STM32G08x microcontrollers
- Added support of STM32L010 microcontrollers
- Flash memory size displayed with debug interface
- Extended ST-LINK server interface support to Linux® and macOS®
- User interface enhancements
- Added contextual menu in main panel for programming, verification, and saving
- Added support of *.binary* files
- Added support of Unicode® file path
- New panel for external loaders; possibility to search and filter with the loader or board name

### 3.22.2 Fixed issues

**Table 23. Main issues fixed in STM32CubeProgrammer v1.3.0**

ID	Summary
54212	STM32CubeProg could not display complete MCU list.
54700	Issue with file path including Chinese characters (double-byte characters).
55156	Error with hex file programming with option "run after programming".

### 3.22.3 Known problems and limitations

- Read/write operations fail with the CAN interface.
- The use of the UART bootloader prevents from increasing the RDP level and programming the second bank of Option Bytes, or from enabling the two user secure areas simultaneously on STM32H7 microcontrollers.
- Programming over USB bootloader is not reliable with USB2.0 for some devices.
- External memory programming is only available with ST-LINK.
- Installing multiple instances of the same version of the tool in the same directory under Windows® leads to issues when uninstalling.
- The STLinkV3-I2C bridge may not work correctly with STM32F4 series, STM32F7 series, and STM32H7 series.

## 3.23 STM32CubeProgrammer v1.2.1 release information

### 3.23.1 New features

- Full-chip erase enabled for STM32L0 series and STM32L1 series
- Enhanced connection to STM32L0 series and STM32L1 with STLINK-V3
- Added support of Quad-SPI flash loaders:
  - N25Q128A\_STM32F7508-DISCO
  - MX25L512G\_STM32F7308-DISCO
  - MT25TL01G\_STM32H743I-EVAL
  - MT25TL01G\_STM32H747-EVAL

### 3.23.2 Fixed issues

**Table 24. Main issues fixed in STM32CubeProgrammer v1.2.1**

ID	Summary
53000	[GUI-memory edition] UART memory editions do not work
53496	[Launcher-java10] The tool is not launched in Windows10 64 bits with Java10
54292	[USB] Connection time increases after every disconnect/connect with DFU interface

### 3.23.3 Known problems and limitations

- Read/write operations fail with the CAN interface.
- The use of the UART bootloader prevents from increasing the RDP level and from programming the second bank of Option Bytes, or from enabling the two user secure areas simultaneously on STM32H7 microcontrollers.
- Programming over USB bootloader is not reliable with USB2.0 for some devices.
- External memory programming is only available with ST-LINK.
- Installing multiple instances of the same version of the tool in the same directory under Windows® leads to issues when uninstalling.
- STLinkV3-I2C bridge may not work correctly with STM32F4 series, STM32F7 series, and STM32H7 series.

## 3.24 STM32CubeProgrammer v1.2.0 release information

### 3.24.1 New features

- Add support of STLINK-V3
- Add support of STM32L41x microcontrollers
- Listing of the connected ST-LINK probes using the `--list` command
- Digitally signed USB DFU driver for STM32 bootloader
- Add support of ST-LINK server interface

### 3.24.2 Known problems and limitations

- Read/write operations fail with the CAN interface.
- The use of the UART bootloader prevents from increasing the RDP level and from programming the second bank of Option Bytes, or from enabling the two user secure areas simultaneously on STM32H7 microcontrollers.
- Programming over USB bootloader is not reliable with USB2.0 for some devices.
- External memory programming is only available with ST-LINK.
- Installing multiple instances of the same version of the tool in the same directory under Windows® leads to issues when uninstalling.

- STLinkV3-I2C bridge may not work correctly with STM32F4 series, STM32F7 series, and STM32H7 series.

## 3.25 STM32CubeProgrammer v1.1.0 release information

### 3.25.1 New features

- Add support of STM32F7x0 Value line and STM32H750 Value line
- Add support of M29W128GL external flash memory programming on STM32H743I-EVAL
- Dump device memory into an hex/srec/bin file
- Add Core debug commands in command-line interface
- Add support of data EEPROM programming on STM32L0 series and STM32L1 series

### 3.25.2 Known problems and limitations

- The use of the UART bootloader prevents from increasing the RDP level and from programming the second bank of option bytes, or from enabling the two user secure areas simultaneously on STM32H7 microcontrollers.
- Programming over USB bootloader is not reliable with USB2.0 for some devices.
- External memory programming is only available with ST-LINK.
- Installing multiple instances of the same version of the tool in the same directory under Windows® leads to issues when uninstalling.

## 3.26 STM32CubeProgrammer v1.0.0 release information

### 3.26.1 New features

- STM32 flash programming and erasing over ST-LINK debug probe (JTAG/SWD) and over bootloader interfaces UART and USB DFU
- STM32 option bytes detailed display with description of each bit field
- Option bytes programming over ST-LINK debug probe (JTAG/SWD) and over bootloader interfaces UART and USB DFU
- External memories programming over ST-LINK debug probe (JTAG/SWD) for STM32 microcontroller evaluation and discovery boards
- Read, display and programming of binary files, ELF files, Intel hex files and Motorola Srecord files
- Read and display of STM32 microcontroller memory content
- Command line and graphical user interface
- Generation of secure firmware using the STM32 Trusted Package Creator tool

### 3.26.2 Known problems and limitations

- The use of the UART bootloader prevents from increasing the RDP level and from programming the second bank of option bytes, or from enabling the two user secure areas simultaneously on STM32H7 microcontrollers.
- Programming over USB bootloader is not reliable with USB2.0 for some devices.
- The erase command is not supported with data EEPROM on STM32L0 and STM32L1.
- External memory programming is only available with ST-LINK.
- Installing multiple instances of the same version of the tool in the same directory under Windows® leads to issues when uninstalling.

## Revision history

Table 25. Document revision history

Date	Revision	Changes
24-Nov-2017	1	Initial release.
12-Apr-2018	2	Part number changed to STM32CubeProg.
19-Jul-2018	3	Added information related to STM32CubeProg 1.1.0.
07-Sep-2018	4	Added information related to STM32CubeProg 1.2.0.
15-Oct-2018	5	Added information related to STM32CubeProg 1.2.1.
15-Nov-2018	6	Added information related to STM32CubeProg 1.3.0.
20-Dec-2018	7	Added information related to STM32CubeProg 1.4.0.
25-Feb-2019	8	Added information related to STM32CubeProg 2.0.0.
23-Apr-2019	9	Added information related to STM32CubeProg 2.1.0.
11-Oct-2019	10	Added information related to STM32CubeProg 2.2.0.
08-Nov-2019	11	Added information related to STM32CubeProg 2.2.1.
20-Dec-2019	12	Added information related to STM32CubeProg 2.3.0.
24-Feb-2020	13	Added information related to STM32CubeProg 2.4.0.
24-Jul-2020	14	Added information related to STM32CubeProg 2.5.0.
18-Nov-2020	15	Added information related to STM32CubeProg 2.6.0. Updated <i>Software requirements</i> .
12-Mar-2021	16	Added information related to STM32CubeProg 2.7.0.
22-Jul-2021	17	Added information related to STM32CubeProg 2.8.0.
29-Nov-2021	18	Added information related to STM32CubeProg 2.9.0.
04-Mar-2022	19	Added information related to STM32CubeProg 2.10.0.
28-Jun-2022	20	Added information related to STM32CubeProg 2.11.0.
25-Nov-2022	21	Added information related to STM32CubeProg 2.12.0.
27-Feb-2023	22	Added information related to STM32CubeProg 2.13.0. Updated the bootloader interfaces in <i>Overview</i> .
31-Mar-2023	23	Added information related to STM32CubeProg 2.13.1.
10-Jul-2023	24	Added information related to STM32CubeProg 2.14.0. Updated <i>Supported operating systems and architectures</i> .
12-Nov-2023	25	Added information related to STM32CubeProg 2.15.0. Updated <i>Licensing</i> .
10-Jan-2024	26	Added enhanced security for software updates in the <i>New features</i> of STM32CubeProg 2.15.0.
19-Mar-2024	27	Added information related to STM32CubeProg 2.16.0. Updated <i>Supported operating systems and architectures</i> .
25-Jun-2024	28	Added information related to STM32CubeProg 2.17.0.
22-Nov-2024	29	Added information related to STM32CubeProg 2.18.0. Updated <i>Supported operating systems and architectures</i> .

## Contents

<b>1</b>	<b>General information</b>	<b>2</b>
1.1	Overview	2
1.2	Host PC system requirements	2
1.3	Setup procedure	2
1.4	Licensing	2
<b>2</b>	<b>STM32CubeProgrammer v2.18.0 release information</b>	<b>3</b>
2.1	New features	3
2.2	Fixed issues	3
2.3	Known problems and limitations	5
<b>3</b>	<b>Previous release information</b>	<b>7</b>
3.1	STM32CubeProgrammer v2.17.0 release information	7
3.1.1	New features	7
3.1.2	Fixed issues	7
3.1.3	Known problems and limitations	8
3.2	STM32CubeProgrammer v2.16.0 release information	9
3.2.1	New features	9
3.2.2	Fixed issues	9
3.2.3	Known problems and limitations	10
3.3	STM32CubeProgrammer v2.15.0 release information	11
3.3.1	New features	11
3.3.2	Fixed issues	11
3.3.3	Known problems and limitations	12
3.4	STM32CubeProgrammer v2.14.0 release information	13
3.4.1	New features	13
3.4.2	Fixed issues	13
3.4.3	Known problems and limitations	14
3.5	STM32CubeProgrammer v2.13.1 release information	15
3.5.1	New features	15
3.5.2	Fixed issues	15
3.5.3	Known problems and limitations	15
3.6	STM32CubeProgrammer v2.13.0 release information	16
3.6.1	New features	16
3.6.2	Fixed issues	16
3.6.3	Known problems and limitations	17
3.7	STM32CubeProgrammer v2.12.0 release information	18

3.7.1	New features	18
3.7.2	Fixed issues	18
3.7.3	Known problems and limitations	20
3.8	STM32CubeProgrammer v2.11.0 release information	21
3.8.1	New features	21
3.8.2	Fixed issues	21
3.8.3	Known problems and limitations	22
3.9	STM32CubeProgrammer v2.10.0 release information	22
3.9.1	New features	22
3.9.2	Fixed issues	23
3.9.3	Known problems and limitations	23
3.10	STM32CubeProgrammer v2.9.0 release information	24
3.10.1	New features	24
3.10.2	Fixed issues	24
3.10.3	Known problems and limitations	24
3.11	STM32CubeProgrammer v2.8.0 release information	24
3.11.1	New features	24
3.11.2	Fixed issues	25
3.11.3	Known problems and limitations	25
3.12	STM32CubeProgrammer v2.7.0 release information	26
3.12.1	New features	26
3.12.2	Fixed issues	26
3.12.3	Known problems and limitations	26
3.13	STM32CubeProgrammer v2.6.0 release information	27
3.13.1	New features	27
3.13.2	Fixed issues	27
3.13.3	Known problems and limitations	28
3.14	STM32CubeProgrammer v2.5.0 release information	28
3.14.1	New features	28
3.14.2	Fixed issues	28
3.14.3	Known problems and limitations	29
3.15	STM32CubeProgrammer v2.4.0 release information	29
3.15.1	New features	29
3.15.2	Fixed issues	29
3.15.3	Known problems and limitations	30
3.16	STM32CubeProgrammer v2.3.0 release information	30
3.16.1	New features	30
3.16.2	Fixed issues	30

3.16.3	Known problems and limitations	30
3.17	STM32CubeProgrammer v2.2.1 release information	31
3.17.1	New features	31
3.17.2	Fixed issues	31
3.17.3	Known problems and limitations	31
3.18	STM32CubeProgrammer v2.2.0 release information	31
3.18.1	New features	31
3.18.2	Fixed issues	31
3.18.3	Known problems and limitations	32
3.19	STM32CubeProgrammer v2.1.0 release information	32
3.19.1	New features	32
3.19.2	Fixed issues	32
3.19.3	Known problems and limitations	32
3.20	STM32CubeProgrammer v2.0.0 release information	33
3.20.1	New features	33
3.20.2	Fixed issues	33
3.20.3	Known problems and limitations	33
3.21	STM32CubeProgrammer v1.4.0 release information	33
3.21.1	New features	33
3.21.2	Fixed issues	33
3.21.3	Known problems and limitations	34
3.22	STM32CubeProgrammer v1.3.0 release information	34
3.22.1	New features	34
3.22.2	Fixed issues	34
3.22.3	Known problems and limitations	34
3.23	STM32CubeProgrammer v1.2.1 release information	35
3.23.1	New features	35
3.23.2	Fixed issues	35
3.23.3	Known problems and limitations	35
3.24	STM32CubeProgrammer v1.2.0 release information	35
3.24.1	New features	35
3.24.2	Known problems and limitations	35
3.25	STM32CubeProgrammer v1.1.0 release information	36
3.25.1	New features	36
3.25.2	Known problems and limitations	36
3.26	STM32CubeProgrammer v1.0.0 release information	36
3.26.1	New features	36



---

3.26.2	Known problems and limitations . . . . .	36
<b>Revision history</b>	. . . . .	<b>37</b>

## List of tables

<b>Table 1.</b>	STM32CubeProgrammer v2.18.0 release summary . . . . .	1
<b>Table 2.</b>	Main issues fixed in STM32CubeProgrammer v2.18.0 . . . . .	3
<b>Table 3.</b>	Main issues fixed in STM32CubeProgrammer v2.17.0 . . . . .	7
<b>Table 4.</b>	Main issues fixed in STM32CubeProgrammer v2.16.0 . . . . .	9
<b>Table 5.</b>	Main issues fixed in STM32CubeProgrammer v2.15.0 . . . . .	11
<b>Table 6.</b>	Main issues fixed in STM32CubeProgrammer v2.14.0 . . . . .	13
<b>Table 7.</b>	Main issues fixed in STM32CubeProgrammer v2.13.0 . . . . .	16
<b>Table 8.</b>	Main issues fixed in STM32CubeProgrammer v2.12.0 . . . . .	18
<b>Table 9.</b>	Main issues fixed in STM32CubeProgrammer v2.11.0 . . . . .	21
<b>Table 10.</b>	Main issues fixed in STM32CubeProgrammer v2.10.0 . . . . .	23
<b>Table 11.</b>	Main issues fixed in STM32CubeProgrammer v2.9.0 . . . . .	24
<b>Table 12.</b>	Main issues fixed in STM32CubeProgrammer v2.8.0 . . . . .	25
<b>Table 13.</b>	Main issues fixed in STM32CubeProgrammer v2.7.0 . . . . .	26
<b>Table 14.</b>	Main issues fixed in STM32CubeProgrammer v2.6.0 . . . . .	27
<b>Table 15.</b>	Main issues fixed in STM32CubeProgrammer v2.5.0 . . . . .	28
<b>Table 16.</b>	Main issues fixed in STM32CubeProgrammer v2.4.0 . . . . .	29
<b>Table 17.</b>	Main issues fixed in STM32CubeProgrammer v2.3.0 . . . . .	30
<b>Table 18.</b>	Main issue fixed in STM32CubeProgrammer v2.2.1 . . . . .	31
<b>Table 19.</b>	Main issues fixed in STM32CubeProgrammer v2.2.0 . . . . .	31
<b>Table 20.</b>	Main issues fixed in STM32CubeProgrammer v2.1.0 . . . . .	32
<b>Table 21.</b>	Main issues fixed in STM32CubeProgrammer v2.0.0 . . . . .	33
<b>Table 22.</b>	Main issues fixed in STM32CubeProgrammer v1.4.0 . . . . .	33
<b>Table 23.</b>	Main issues fixed in STM32CubeProgrammer v1.3.0 . . . . .	34
<b>Table 24.</b>	Main issues fixed in STM32CubeProgrammer v1.2.1 . . . . .	35
<b>Table 25.</b>	Document revision history . . . . .	37

**IMPORTANT NOTICE – READ CAREFULLY**

STMicroelectronics NV and its subsidiaries (“ST”) reserve the right to make changes, corrections, enhancements, modifications, and improvements to ST products and/or to this document at any time without notice. Purchasers should obtain the latest relevant information on ST products before placing orders. ST products are sold pursuant to ST’s terms and conditions of sale in place at the time of order acknowledgment.

Purchasers are solely responsible for the choice, selection, and use of ST products and ST assumes no liability for application assistance or the design of purchasers’ products.

No license, express or implied, to any intellectual property right is granted by ST herein.

Resale of ST products with provisions different from the information set forth herein shall void any warranty granted by ST for such product.

ST and the ST logo are trademarks of ST. For additional information about ST trademarks, refer to [www.st.com/trademarks](http://www.st.com/trademarks). All other product or service names are the property of their respective owners.

Information in this document supersedes and replaces information previously supplied in any prior versions of this document.

© 2024 STMicroelectronics – All rights reserved